


TMEC (TITAN CABLE MANAGEMENT RACK END CAP) ASSEMBLY INSTRUCTIONS


PARTS & HARDWARE



STEP 1

PARTS REQUIRED:

- 2 X "A"
- 3 X "E"




BACK VIEW

STEP 2

PARTS REQUIRED:

- 2 X "B"
- 8 X "E"
- 8 X "F"



BACK VIEW
FINGERS WERE HIDDEN FOR CLARITY




1 INNOVATION DRIVE - DES PLAINES, IL 60016

STEP 3-A
FOR 6" & 10" WIDE FINGERS

- PARTS REQUIRED:**
- 2 X "C"
 - 8 X "E" (FOR 6" FINGERS)
 - 4 X "E" (FOR 10" FINGERS)

ONLY REQUIRED FOR 6" FINGERS




BACK VIEW

STEP 3-B
FOR 16" & 30" WIDE FINGERS

- PARTS REQUIRED:**
- 2 X "C"
 - 8 X "E" (FOR 16" FINGERS)
 - 4 X "E" (FOR 30" FINGERS)

ONLY REQUIRED FOR 16 " FINGERS



BACK VIEW




1 INNOVATION DRIVE - DES PLAINES, IL 60016

L:\Engineering\IMS Product Project\TCM\Work_Instructions\TMECINST

STEP 4


PARTS REQUIRED:

- 1 X "D"
- 8 X "F"



BACK VIEW
FINGERS WERE HIDDEN FOR CLARITY

FINAL VIEW



FRONT VIEW



1 INNOVATION DRIVE - DES PLAINES, IL 60016

L:\Engineering\IMS Product Project\TCM\Work_Instructions\TMECINST